




## Basevan.com General Inspection

### Inspection details

Name of inspector	Wallis
Date of inspection	10/04/2025
Signature	

### Vehicle details

Vehicle registration	WJ19YDV
Vehicle chassis no.	ZFA25000002J91634
Miles (if in km, multiply by 0.62)	212299
Make	Fiat
Model	Ducato
Transmission	Manual, 6 speed
Factory immobiliser installed	Yes
Speed limiter installed	N/A
Drive configuration	FWD
Gross Vehicle Weight (kg)	4250
Towing capacity	2250
Tow bar installed	No

### Off side front

Age (month/year) Manufactured	19/24
Make, brand.	Michelin
Tyre size	225/75/R16
Pressure 1	68
Pressure 2	
Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	4
General comments	



## Basevan.com General Inspection

Images of tyre



### Near side front

Age (month/year) Manufactured	19/24
Make, brand.	Michelin
Tyre size	225/75/R16
Pressure 1	68
Pressure 2	
Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	5
General comments	



## Basevan.com General Inspection

Images of tyre



### near side rear

Age (month/year) Manufactured	25/23
Make, brand.	Michelin
Tyre size	225/75/R16
Pressure 1	78
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	7
General comments	





## Basevan.com General Inspection

Images of tyre



### Off side rear

Age (month/year) Manufactured	21/23
Make, brand.	Michelin
Tyre size	225/75/R16
Pressure 1	76
Pressure 2	
Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	5
General comments	



Basevan.com General Inspection

Images of tyre

off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



## Basevan.com General Inspection

tread depth (mm)	
General comments	
Images of tyre	

### near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

### Spare wheel

Spare installed? (If no, don't fill out)	
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	


### Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	No
Response from in-cab locking button?	Yes
Do all the doors lock from central locking function?	None





## Basevan.com General Inspection

Select the following doors that lock.	O/S Front
Method of locking	Key
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	No
How many keys present at time of inspection?	
Comment	

### In cab checks

Number of seats (cab only)	Driver & 1 passenger
Cab heater check	Does not work
Comment on cab heater	



## Basevan.com General Inspection

Electric windows present	Yes
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	Yes
Charging socket present (cigarette lighter)	Yes
Function working?	N/A
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	Yes
Reverse camera functioning?	Yes
Show any damage or missing items	

## General mechanical checks

Fuel level	1/2 Full
Oil level	Medium
Oil conditon	Service due soon
Start up, chassis battery check	Started without jump pack
Start-up from cold	3 seconds
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	14.1
Chain or Belt driven engine?	Belt
If belt any proof of change?	N/A
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-17
Washer fluid	Full
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	No warning lights
OBD Scan results	





Date Submitted: 10/04/2025 04:35 PM  
Submitted By: office@basevan.com

## Basevan.com General Inspection

### Engine bay photo



### Comment