

Inspection details

Name of inspector	Wallis
Date of inspection	22/04/2025
Signature	Lun

Vehicle details

Vehicle registration	VX58CVN
Vehicle chassis no.	WBD9066552S269892
Miles (if in km, multiply by 0.62)	87026
Make	Mercedes
Model	Sprinter
Transmission	Manual, 6 speed
Factory immobiliser installed	Yes
Speed limiter installed	N/A
Drive configuration	RWD
Gross Vehicle Weight (kg)	5000
Towing capacity	2000
Tow bar installed	No

Off side front

Age (month/year) Manufactured	39/21
Make, brand.	Good Year
Tyre size	205/75/R16
Pressure 1	60
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	



Images of tyre



Near side front

Age (month/year) Manufactured	04/21
Make, brand.	Good Year
Tyre size	
Pressure 1	55
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	



Images of tyre



near side rear

Age (month/year) Manufactured	03/23
Make, brand.	Good Year
Tyre size	205/75/R16
Pressure 1	54
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	



Images of tyre



Off side rear

Age (month/year) Manufactured	03/23
Make, brand.	Good Year
Tyre size	205/75/R16
Pressure 1	56
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	




Images of tyre



off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	03/23
Make, brand.	Good Year
Tyre size	205/75/R16
Pressure 1	56
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None





tread depth (mm)	9
General comments	
Images of tyre	<image/>

near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	03/23
Make, brand.	Good Year
Tyre size	205/75/R16
Pressure 1	60
Pressure 2	



Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	
Images of tyre	

Spare wheel

Spare installed? (If no, don't fill out)	Yes
Age (month/year) Manufactured	50/07
Make, brand.	Good Year
Tyre size	205/75/R16



Pressure 1	43
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	Yes
Do all the doors lock from central locking function?	All
Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes



How many keys present at time of inspection?	
Comment	
In cab checks	
Number of seats (cab only)	Driver & 1 passenger
Cab heater check	Works on all settings
Comment on cab heater	

Driver side function, Passenger side function

Electric windows present

Air conditioning present

Cab windows function check

Charging socket present (cigarette lighter)

Yes

No

Yes



Function working?	N/A
Radio / Media system fitted?	No
Radio / media system check	N/A not installed
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full	
Oil level	Full	
Oil conditon	Clean	
Start up, chassis battery check	Started without jump pack	
Start-up from cold	3 seconds	
Exhaust smoke from cold	Normal	
Output Voltage of Alternator test	14.1	
Chain or Belt driven engine?	Chain	
If belt any proof of change?		
Coolant condition	Clean	
Coolant level	Full	
Anti-freeze temperature check	-23	
Washer fluid	Full	
Brake fluid	Full	
Power steering fluid	Maximum	
Dashboard warning light	No warning lights	
OBD Scan results		



Engine bay photo



Comment