




BaseVan Initial Inspection

Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	13/09/2023
Signature	

Vehicle details

Vehicle registration	NX16CUA
Vehicle chassis no.	
Miles (if in km, multiply by 0.62)	134608
Make	Vauxhall
Model	Movano
Transmission	Manual, 6 speed
Factory immobiliser installed	Yes
Speed limiter installed	No
Drive configuration	RWD
Gross vehicle weight	4600kg
Towing capacity	3000kg
Tow bar installed	No

Off side front

Age (month/year) Manufactured	41/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	good tyre relatively new



BaseVan Initial Inspection

Images of tyre



Near side front

Age (month/year) Manufactured	41/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	good tyre relatively new



BaseVan Initial Inspection

Images of tyre



near side rear

Age (month/year) Manufactured	25/20
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	4
General comments	pretty good tyre some wear but good life left



BaseVan Initial Inspection

Images of tyre



Off side rear

Age (month/year) Manufactured	43/21
Make, brand.	Continental
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	good tyre good tread



BaseVan Initial Inspection

Images of tyre	
----------------	--

off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	25/20
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	5
General comments	decent tyre good life left



BaseVan Initial Inspection

Images of tyre




near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	25/20
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None



BaseVan Initial Inspection

tread depth (mm)	5
General comments	good tyre good life left
Images of tyre	

Spare wheel

Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	



BaseVan Initial Inspection

Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	Yes
Do all the doors lock from central locking function?	All
Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes



BaseVan Initial Inspection

How many keys present at time of inspection?



Comment

all works well

In cab checks

Number of seats (cab only)	Driver & 2 passenger
Cab heater check	
Comment on cab heater	
Electric windows present	Yes
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes



BaseVan Initial Inspection

Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full
Oil level	Medium, Amended to correct level
Oil condition	Clean
Start up, chassis battery check	Started without jump pack
Start-up from cold	Instant
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	14.1
Chain or Belt driven engine?	Chain
If belt any proof of change?	-
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-14
Washer fluid	Full
Brake fluid	Full
Power steering fluid	N/A
Dashboard warning light	No warning lights
OBD Scan results	
Engine bay photo	
Comment	