




## BaseVan Initial Inspection

### Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	12/02/2024
Signature	

### Vehicle details

Vehicle registration	YJ56UVD
Vehicle chassis no.	ZCFC358300D324145
Miles (if in km, multiply by 0.62)	29450
Make	Iveco
Model	Daily
Transmission	Manual, 5 speed
Factory immobiliser installed	Yes
Speed limiter installed	No
Drive configuration	RWD
Gross vehicle weight	3500kg
Towing capacity	1800
Tow bar installed	Yes

### Off side front

Age (month/year) Manufactured	20/17
Make, brand.	Budget
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	6
General comments	good tyre decent life left



## BaseVan Initial Inspection

Images of tyre



### Near side front

Age (month/year) Manufactured	20/17
Make, brand.	Budget
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	4
General comments	good tyre but worn



## BaseVan Initial Inspection

Images of tyre



### near side rear

Age (month/year) Manufactured	20/17
Make, brand.	Budget
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	great tyre loads of life





## BaseVan Initial Inspection

Images of tyre



### Off side rear

Age (month/year) Manufactured	20/17
Make, brand.	Budget
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	good tyre lots of life



## BaseVan Initial Inspection

Images of tyre



### off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



## BaseVan Initial Inspection

tread depth (mm)	
General comments	
Images of tyre	

### near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

### Spare wheel

Spare installed? (If no, don't fill out)	
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	


### Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	No
Do all the doors lock from central locking function?	All





## BaseVan Initial Inspection

Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	works as intended

### In cab checks

Number of seats (cab only)	Driver & 2 passenger
Cab heater check	Works on all settings
Comment on cab heater	works as intended



## BaseVan Initial Inspection

Electric windows present	No
Cab windows function check	Passenger side function, Driver side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

## General mechanical checks

Fuel level	3/4 Full
Oil level	Full
Oil conditon	Clean
Start up, chassis battery check	Started without jump pack
Start-up from cold	Instant
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	14.2v
Chain or Belt driven engine?	Belt
If belt any proof of change?	-
Coolant condition	Clean
Coolant level	Medium
Anti-freeze temperature check	-15
Washer fluid	Full
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	No warning lights
OBD Scan results	
Engine bay photo	
Comment	