




## Basevan.com General Inspection

### Inspection details

Name of inspector	Wallis
Date of inspection	15/04/2025
Signature	

### Vehicle details

Vehicle registration	PO60KUC
Vehicle chassis no.	ZCFC4091005822542
Miles (if in km, multiply by 0.62)	16527
Make	Iveco
Model	Daily
Transmission	Manual, 5 speed
Factory immobiliser installed	Yes
Speed limiter installed	N/A
Drive configuration	RWD
Gross Vehicle Weight (kg)	4200
Towing capacity	3500
Tow bar installed	No

### Off side front

Age (month/year) Manufactured	35/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	64
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	7
General comments	



## Basevan.com General Inspection

Images of tyre



### Near side front

Age (month/year) Manufactured	34/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	64
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	



## Basevan.com General Inspection

Images of tyre



### near side rear

Age (month/year) Manufactured	34/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	60
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	7
General comments	





## Basevan.com General Inspection

Images of tyre



### Off side rear

Age (month/year) Manufactured	32/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	63
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	



## Basevan.com General Inspection

Images of tyre




### off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	32/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	64
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None



## Basevan.com General Inspection

tread depth (mm)	8
General comments	
Images of tyre	


### near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	34/21
Make, brand.	Michelin
Tyre size	195/75/R16
Pressure 1	64
Pressure 2	





## Basevan.com General Inspection

Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	
Images of tyre	

## Spare wheel

Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	



## Basevan.com General Inspection

Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

## Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	N/A
Do all the doors lock from central locking function?	All
Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes





## Basevan.com General Inspection

How many keys present at time of inspection?



Comment

### In cab checks

Number of seats (cab only)	Driver & 2 passenger
Cab heater check	Works on all settings
Comment on cab heater	
Electric windows present	Yes
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	Yes
Charging socket present (cigarette lighter)	Yes



## Basevan.com General Inspection

Function working?	N/A
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

## General mechanical checks

Fuel level	1/2 Full
Oil level	Medium
Oil conditon	Clean
Start up, chassis battery check	Started without jump pack
Start-up from cold	2 seconds
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	14.1
Chain or Belt driven engine?	Belt
If belt any proof of change?	N/A
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-17
Washer fluid	Full
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	No warning lights
OBD Scan results	



## Basevan.com General Inspection

Engine bay photo



Comment