




## Basevan.com General Inspection

### Inspection details

Name of inspector	Wallis
Date of inspection	16/04/2025
Signature	

### Vehicle details

Vehicle registration	YJ14HSD
Vehicle chassis no.	VF1MAF4SE50062278
Miles (if in km, multiply by 0.62)	51313
Make	Renault
Model	Master
Transmission	Manual, 6 speed
Factory immobiliser installed	Yes
Speed limiter installed	N/A
Drive configuration	FWD
Gross Vehicle Weight (kg)	3500
Towing capacity	2500
Tow bar installed	No


### Off side front

Age (month/year) Manufactured	47/20
Make, brand.	Good Year
Tyre size	225/65/R16
Pressure 1	30
Pressure 2	
Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	5
General comments	



## Basevan.com General Inspection

Images of tyre




### Near side front

Age (month/year) Manufactured	42/20
Make, brand.	Good Year
Tyre size	225/65/R16
Pressure 1	30
Pressure 2	
Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	5
General comments	



## Basevan.com General Inspection

Images of tyre



### near side rear

Age (month/year) Manufactured	42/13
Make, brand.	Michelin
Tyre size	225/65/R16
Pressure 1	46
Pressure 2	
Wearing / Perishing (inner)	Replace soon
Wearing / Perishing (outer)	Replace soon
tread depth (mm)	3
General comments	





## Basevan.com General Inspection

Images of tyre



### Off side rear

Age (month/year) Manufactured	35/22
Make, brand.	Other (comment)
Tyre size	225/65/R16
Pressure 1	40
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	7
General comments	



Basevan.com General Inspection

Images of tyre

off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



## Basevan.com General Inspection

tread depth (mm)	
General comments	
Images of tyre	

### near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

### Spare wheel

Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	


### Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	Yes
Do all the doors lock from central locking function?	All





## Basevan.com General Inspection

Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	

### In cab checks

Number of seats (cab only)	Driver & 2 passenger
Cab heater check	Works on all settings
Comment on cab heater	



## Basevan.com General Inspection

Electric windows present	Yes
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	Yes
Charging socket present (cigarette lighter)	Yes
Function working?	N/A
Radio / Media system fitted?	No
Radio / media system check	N/A not installed
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

## General mechanical checks

Fuel level	1/2 Full
Oil level	Medium
Oil conditon	Service due soon
Start up, chassis battery check	Started without jump pack
Start-up from cold	2 seconds
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	14.1
Chain or Belt driven engine?	Chain
If belt any proof of change?	N/A
Coolant condition	Clean
Coolant level	Medium
Anti-freeze temperature check	-17
Washer fluid	Medium
Brake fluid	Full
Power steering fluid	Miniumum
Dashboard warning light	No warning lights
OBD Scan results	





## Basevan.com General Inspection

Engine bay photo



Comment