




Basevan.com General Inspection

Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	17/04/2025
Signature	

Vehicle details

Vehicle registration	LG57KMV
Vehicle chassis no.	VN1F9C1H637523301
Miles (if in km, multiply by 0.62)	50,893
Make	Vauxhall
Model	Movano
Transmission	Manual, 6 speed
Factory immobiliser installed	Yes
Speed limiter installed	Yes
Drive configuration	FWD
Gross Vehicle Weight (kg)	3500
Towing capacity	2500
Tow bar installed	No

Off side front

Age (month/year) Manufactured	49/20
Make, brand.	Hankook
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	virtually brand new



Basevan.com General Inspection

Images of tyre



Near side front

Age (month/year) Manufactured	49/20
Make, brand.	Hankook
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	matches offside



Basevan.com General Inspection

Images of tyre




near side rear

Age (month/year) Manufactured	51/22
Make, brand.	Continental
Tyre size	235/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	possible reason for recent tyre pictured below + Irregular size



Basevan.com General Inspection

Images of tyre





Basevan.com General Inspection



Off side rear

Age (month/year) Manufactured	39/16
Make, brand.	Cooper
Tyre size	225/65/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Dangerous, replace
Wearing / Perishing (outer)	Dangerous, Replace
tread depth (mm)	7
General comments	Perishing BAD




Basevan.com General Inspection

Images of tyre





Basevan.com General Inspection



off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	N/A
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



Basevan.com General Inspection

tread depth (mm)	
General comments	
Images of tyre	

near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	N/A
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Spare wheel


Spare installed? (If no, don't fill out)	N/A
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	Yes
Do all the doors lock from central locking function?	All



Basevan.com General Inspection

Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Key, Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	
	Rear doors lock only on deadlock / key

In cab checks

Number of seats (cab only)	Driver & 1 passenger
Cab heater check	Works on all settings
Comment on cab heater	1,2,3,4 perfect



Basevan.com General Inspection

Electric windows present	No
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	


General mechanical checks

Fuel level	1/2 Full
Oil level	Full
Oil conditon	Clean
Start up, chassis battery check	Started without jump pack
Start-up from cold	Instant
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	13.9
Chain or Belt driven engine?	Belt
If belt any proof of change?	No
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-16
Washer fluid	Medium
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	No warning lights
OBD Scan results	



Basevan.com General Inspection

Engine bay photo



Comment

sweet mechanically